

# Mesthoipalya Lake



RANGE: JAKKASANDRA

HOBLI: BEGURU

TALUK: BANGALORE SOUTH.

## SURVEY NO: 30 LAKE

Sketch Prepared As per the Order of Honorable High Court Vide No: WP NO:6961 / 2020 PIL Dated:15/06/2021



Scale: 1cm=3960

### DETAIL:-

1. Sketch Prepared As per the direction of DDLR Letter No: ಚಾಂಸ/ಭೂಸಂ/ಶಾಂ(6)ಎವ/21/2021 ದಿನಾಂಕ:28/06/2021 and memo of ADLR Bangalore South No: ಭೂಸಂ/ಪ.ಆರ್/ಇಶರೆ:273/2020-21 ದಿನಾಂಕ:02/05/2024
2.  Color Shows the privet encroachment details.
3. Survey Department(Land Records) is only responsible fo measurement and extent of the lake.
4. The measurement carried out as per Survey Records in presence of BBMP Eengeenier
5. As fencing of the Lake boundary is alreadydone by the BBMP as per previous survey sketch during present field inspection that fence (Chain and Link Fencing) is still in extent only leftout area of the Lake is now demarketed as as enchroachment as per Survey document.
6. Lake Details as below ( The Details of the Encroachment in lake are need to be verify from conserved authority)

Sl. No	LAKE SY NO	EXTENT OF THE LAKE		DETAILS OF THE ENCHROCHMENT IN LAKE						VACANT LAND (A-G)	REMARKS
		AS PER AKHARABAND (A-G)	AS PER MEASUREMENT (A-G)	PRAVITE ENCHROCHMENT			GOVT ENCHROCHMENT				
				Block No	TYPE OF ENCHROCHMENT	EXTENT (A-G)	Block No	TYPE OF ENCHROCHMENT	EXTENT (A-G)		
1	30	11-21	11-21	-	-	-	I	BDA LAYOUT	0-08	-	
2				-	-	-	II		1-10	-	
3				-	-	-	III	BSNL Compound	0-0.08	-	
TOTAL									1-18.08		

*[Signature]*  
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ಅಲ್ಯೂಕು.

*[Signature]*  
ಪರ್ಯವೇಕ್ಷಕರು  
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ಅಲ್ಯೂಕು  
ಬೆಂಗಳೂರು

*[Signature]*  
Office Certified

ಧೂವಾವಿಲೆಗಳ ಸಹಾಯಕ ನಿರ್ದೇಶಕರು,  
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ಅಲ್ಯೂಕು,  
ಬೆಂಗಳೂರು.