
## VILLAGE: VAJARAHALLI, HOBLI: UTTARAHALLI, TALUK: BANGALORE SOUTH. SURVEY NO: 36 LAKE

{Lake Sketch Prepared As per the Order of Honarable High Court Vide No: WP NO:38401 / 2014 PIL Dated:02/06/2021}





## **DETAIL:-**

- 1. Sketch Prepared As per the direction of DDLR Letter No: ಜಿತಾಂಸ್ಮಧೂಉನಿ/ತಾಂ(6)ವಿವ/21/2021 ದಿನಾಂಕ:28/06/2021 and memo of ADLR Bangalore South No: ಭೂಸನಿ/ಪಿ.ಆರ್/ಇತರೆ:273/2020–21 ದಿನಾಂಕ:02/05/2024
- Color Shows the Road encroachment details.
- 3. Survey Department(Land Records) is only responsible for measurement and extent of the lake.
- 4. The measurement carried out as per Survey Records in presence of BBMP Engeenier
- As fencing of the Lake boundary is alreadydone by the BBMP as per previous survey sketch during present field
  inspection that fence (Chain and Link Fencing) is still in extent only leftout area of the Lake is now demarketed as
  as enchrochment as per Survey document.
- 6. Lake Details as below (The Details of the Encrochment in lake are need to be verify from conserned authority)

	No	LAKE SY NO	EXTENT OF THE LAKE		DETAILS OF THE ENCHROCHMENT IN LAKE							VACANT	TOTAL	0	Section 1997
SL			AS PER AKHARABAND (A-G)	AS PER MEASUREMENT ( A-G)	PRAVITE ENCHROCHMENT						Encrochment	LAND	AREA	1	REMARKS
					Block No	TYPE OF ENCROCHMENT	(A-G)	Block No	TYPE OF ENCROCHMENT	(A-G)	( A-G)	( A-G)	1	190	
1	$\neg$	36	02-31	02-31				ACC   Cont.	ROAD		0 - 10.25	02 - 20.75	02 - 31		01 May 1
					14	1/2 m			0 - 10.25	0-10.25				1	

Measurement Carried Date:

ತಿಂದ್ರಶೇಖರ್. ಕೆ ಭೂಮಾಸಕವು

ಬೆಂಗಳೂರು ದಕ್ಷಣ ತಾಗಿ ಕಛೇರಿ.

Executive Mahanagara Palike

White a sound of the sound of t

ಭೂದಾಖಲೆಗಳ ಸಹಾಯಕ ನಿರ್ದೇಶಕ ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು, ಬೆಂಗಳೂರು,

DOUGOSCO