


VILLAGE: KENGERI, HOBLI: KENGERI, TALUK: BANGALORE SOUTH.

SURVEY NO: 58 LAKE

{Lake Sketch Prepared As per the Order of Honorable High Court Vide No: WP NO:38401 / 2014 PIL Dated:02/06/2021}



DETAIL:-

1. Sketch Prepared As per the direction of DDLR Letter No: ಜತಾಂಸ/ಭೂಮಿ/ಶಾಂ(6)ವಿವ/21/2021 ದಿನಾಂಕ:28/06/2021 and memo of ADLR Bangalore South No: ಭೂಮಿ/ಪಿ.ಆರ್/ಇತರೆ:273/2020-21 ದಿನಾಂಕ:02/05/2024
2. Survey Department(Land Records) is only responsible for measurement and extent of the lake.
3. The measurement carried out as per Survey Records in presence of BBMP Engeenier
4. As fencing of the Lake boundary is already done by the BBMP as per previous survey sketch during present field inspection that fence (Chain and Link Fencing) is still in extent only leftout area of the Lake is now demarketed as as enchrochment as per Survey document.
5. Lake Details as below (The Details of the Encroachment in lake are need to be verify from conserved authority)

SL No	LAKE SY NO	EXTENT OF THE LAKE		DETAILS OF THE ENCHROCHMENT IN LAKE						Total Area of Encroachment (A-G)	VACANT LAND (A-G)	TOTAL AREA	REMARKS
		AS PER AKHARABAND (A-G)	AS PER MEASUREMENT (A-G)	PRAVITE ENCHROCHMENT			GOVT ENCHROCHMENT						
				Block No	TYPE OF ENCHROCHMENT	EXTENT (A-G)	Block No	TYPE OF ENCHROCHMENT	EXTENT (A-G)				
1	58	06-02	06-02	—	—	—	—	—	—	—	—	06-02	

Measurement Carried Date:

ಕುಮಾರ್
ಭೂಮಿ
 ಭೂಮಾಪಕರು
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
 24/7/24


Colt
 Executive Engineer, LAKES
 Bruhat Bengaluru Mahanagara Palike

ಶರಣ್
 ಪರೀಕ್ಷಕರು
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
 ಬೆಂಗಳೂರು.

J. Srinivas
 ಭೂದಾಖಲೆಗಳ ಸಹಾಯಕ ನಿರ್ದೇಶಕರು
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
 ಬೆಂಗಳೂರು.

VILLAGE: MAILASANDRA, HOBLI: KENGERI, TALUK: BANGALORE SOUTH.
SURVEY NO: 37 LAKE

{Lake Sketch Prepared As per the Order of Honorable High Court Vide No: WP NO:38401 / 2014 PIL Dated:02/06/2021}



DETAIL:-

- 1.1. Sketch Prepared As per the direction of DDLR Letter No: ಜತಾಂಸ/ಭೂಲುನಿ/ತಾಂ(6)ವಿವ/21/2021 ದಿನಾಂಕ:28/06/2021 and memo of ADLR Bangalore South No: ಭೂಸನಿ/ಪಿ.ಆರ್/ಇಕರೆ:273/2020-21 ದಿನಾಂಕ:02/05/2024
2. █ Color Shows the Road encroachment details.
3. Survey Department(Land Records) is only responsible for measurement and extent of the lake.
4. The measurement carried out as per Survey Records in presence of BBMP Engeenier
5. As fencing of the Lake boundary is alreadydone by the BBMP as per previous survey sketch during present field inspection that fence (Chain and Link Fencing) is still in extent only leftout area of the Lake is now demarketed as encroachment as per Survey document.
6. Lake Details as below (The Details of the Encroachment in lake are need to be verify from conserved authority)

SL No	LAKE SY NO	EXTENT OF THE LAKE		DETAILS OF THE ENCHROCIEMENT IN LAKE						Total Area of Encroachment (A-G)	VACANT LAND (A-G)	TOTAL AREA	REMARKS	
		AS PER AKHARABAND (A-G)	AS PER MEASUREMENT (A-G)	PRAVITE ENCHROCIEMENT			GOVT ENCHROCIEMENT							
				Block No	TYPE OF ENCHROCIEMENT	EXTENT (A-G)	Block No	TYPE OF ENCHROCIEMENT	EXTENT (A-G)					
1	37	06 - 24	06 - 24						0 - 27	0 - 27	0 - 27	5 - 27	06 - 24	

Measurement Carried Date:

ಶಿವರಾಜ್
ಭೂಮಾಪಕರು
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
25/7/24

CE
Executive Engineer, Lakes
Bruhat Bengaluru Mahanagara Palike

Arjun
ಪರೀಕ್ಷಾ ವೇದಿಕೆ
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
ಬೆಂಗಳೂರು.

T. S. Lakshmi
ಭೂದಾಖಲೆಗಳ ಸಹಾಯಕ ನಿರ್ದೇಶಕರು,
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು,
ಬೆಂಗಳೂರು.