


VILLAGE: CHUDENAPURA, HOBLI: KENGERI, TALUK: BANGALORE SOUTH.
SURVEY NO: 15 LAKE

{Lake Sketch Prepared As per the Order of Honorable High Court Vide No: WP NO:38401 / 2014 PIL Dated:02/06/2021}



Scale: 1cm=1584cm

DETAIL:-

1. Sketch Prepared As per the direction of DDLR Letter No: ಜತಾಂಸ/ಭೂಲನ/ತಾಂ(6)ಎವ/21/2021 ದಿನಾಂಕ:28/06/2021 and memo of ADLR Bangalore South No: ಭೂಸನ/ಓ.ಆರ್/ಇತರ:273/2020-21 ದಿನಾಂಕ:02/05/2024
2. Survey Department(Land Records) is only responsible for measurement and extent of the lake.
3. The measurement carried out as per Survey Records in presence of BBMP Engeenier
4. As fencing of the Lake boundary is alreadydone by the BBMP as per previous survey sketch during present field inspection that fence (Chain and Link Fencing) is still in extent only leftout area of the Lake is now demarketed as as enchroachment as per Survey document.
5. Lake Details as below (The Details of the Encroachment in lake are need to be verify from conserved authority)

SL No	LAKE SY NO	EXTENT OF THE LAKE		DETAILS OF THE ENCHROCHMENT IN LAKE						Total Area of Enchroachment (A-G)	VACANT LAND (A-G)	TOTAL ARRA	REMARKS
		AS PER AKHARABAND (A-G)	AS PER MEASUREMENT (A-G)	PRAVITE ENCHROCHMENT			GOVT ENCHROCHMENT						
				Block No	TYPE OF ENCHROCHMENT	EXTENT (A-G)	Block No	TYPE OF ENCHROCHMENT	EXTENT (A-G)				
1	15	20-39	20-39	—	—	—	—	—	—	—	—	20-39	

Measurement Carried Date:

KV-madhusu
 ಭೂಮಾಪಕರು
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು


CEA
 Executive Engineer, Lakes
 Bruhat Bengaluru Mahanagara Palike

Praveen
 ಪಟ್ಟಣದ ಅಧ್ಯಕ್ಷರು
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
 ಬೆಂಗಳೂರು.

J. S. Lakshmi
 ಭೂಮಾಪಕಿಗಳ ಸಹಾಯಕ ನಿರ್ದೇಶಕರು,
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು,
 ಬೆಂಗಳೂರು.

VILLAGE: HEMMIGEPURA, HOBLI: KENGERI, TALUK: BANGALORE SOUTH.
SURVEY NO: 61 LAKE

{Lake Sketch Prepared As per the Order of Honorable High Court Vide No: WP NO:38401 / 2014 PIL Dated:02/06/2021}



DETAIL:-

1. Sketch Prepared As per the direction of DDLR Letter No: ಜತಾಂಸ/ಭೂಲಾನಿ/ತಾಂ(6)ಎವ/21/2021 ದಿನಾಂಕ:28/06/2021 and memo of ADLR Bangalore South No: ಭೂಸವ/ಕ.ಆರ್/ಇತರ:273/2020-21 ದಿನಾಂಕ:02/05/2024
2. Color Shows the Road encroachment details.
3. Color Shows the priwet encroachment details.
4. Survey Department(Land Records) is only responsible for measurement and extent of the lake.
5. The measurement carried out as per Survey Records in presence of BBMP Engeenier
6. As fencing of the Lake boundary is alreadydone by the BBMP as per previous survey sketch during present field inspection that fence (Chain and Link Fencing) is still in extent only leftout area of the Lake is now demarketed as as encroachment as per Survey document.

7. Lake Details as below (The Details of the Encroachment in lake are need to be verify from conserved authority)

SL No	LAKE SY NO	EXTENT OF THE LAKE		DETAILS OF THE ENCROACHMENT IN LAKE						Total Area of Encroachment (A-G)	VACANT LAND (A-G)	TOTAL AREA	REMARKS
		AS PER AKHARABAND (A-G)	AS PER MEASUREMENT (A-G)	Block No	TYPE OF ENCROACHMENT	EXTENT (A-G)	Block No	TYPE OF ENCROACHMENT	EXTENT (A-G)				
1	61	16-15	16-15	I	MUSLIM BARRAKA	0-05	II	ROAD	1-00	1-00	15-15	16-15	

Measurement Carried Date:

V. M. Madhava
 ಭೂಮಾಲೀಕರು
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು

[Signature]
 Executive Engineer, Lakes
 Bruhat Bengaluru Mahanagara Palike

[Signature]
 ಪುನರಾವೇಶಿಣಿ
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
 ಬೆಂಗಳೂರು.

[Signature]
 ಭೂಮಾಲೀಕರ ಸಹಾಯಕ ನಿರ್ದೇಶಕರು,
 ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು,
 ಬೆಂಗಳೂರು.