


Village : Thalaghattapura

Hobli :Uttarahalli

Taluk : Bengaluru South

District : Bengaluru Urban

Lake Sketch prepared, as per the Order of HON'BLE HIGH COURT vide W.P.NO: 6961/2020 Dated: 15-06-2021**Lake Survey Number : 73****DETAILS:**

1. Sketch prepared, as per the directions of DDLR letter NO: ಜಿ.ತಾಂ.ಸ/ಭೂ.ಸಿ/ತಾಂ(6) ವಿ.ವ:21/2021 ದಿ:28-06-2021 and memo of ADLR, Bengaluru South NO: ಭೂ.ಸಿ/ಮೋಡಿ/ಇತರೆ/273/2020-21, ದಿ: 02-05-2024
2. ■ Color Shows the government encroachment details.
3. ■ Color Shows the private encroachment details.
4. Survey department (land records) is only responsible for measurement and extent of the lake.
5. The measurement carried as per survey records in presence of B.B.M.P Engineer.
6. As fencing of the lake boundary is already done by B.B.M.P as per previous survey sketch during present field inspection that fence (chain And link fencing) is still in extents only left out area of the lake is now demarcated as encroachment as per survey document.
7. Lake details as below: (The details of the encroachment in lake are need to be verify from concerned authority).

Sl No	Lake Sy No.	Extent of the lake		Details of Encroachment in Lake							Remarks
		As per Akarbhanda (A-G)	As per Measurement (A-G)	Private Encroachment			Government Encroachment			Vacant Land A-G	
				Type of Encroachment	Block No.	Extent A-G	Type Encroachment	Block No.	Extent A-G		
1	73	19-16	19-16	-	-	-	B.D.A	I	0-17	-	
2				PRIVATE	II	0-04	--	--	--	--	
3				VACANT	III	0-08	--	--	--	--	
4				PRIVATE	IV	2-00	--	--	--	--	
TOTAL				--	--	2-12	--	--	0-17	16-27	

[Signature]
ಭೂಮಾಪಕರು
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ಜಿಲ್ಲಾ ಅಧಿಕಾರಿ
ಬೆಂಗಳೂರು ನಗರ.

[Signature]
ಪ್ರಾ.ಪಂ. ಅಧಿಕಾರಿ
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ಜಿಲ್ಲಾ ಅಧಿಕಾರಿ
ಬೆಂಗಳೂರು. 23/7/24

[Signature]
ಜಿಲ್ಲಾ ಪಂಚಾಯತ್ ಸಹಾಯಕ ನಿರ್ದೇಶಕರು,
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ಜಿಲ್ಲಾ ಅಧಿಕಾರಿ,
ಬೆಂಗಳೂರು.