

Village : Halgevaderahalli


Hobli : Kengeri

Taluk : Bengaluru South

District : Bengaluru Urban

**Lake Sketch prepared, as per the Order of HON'BLE HIGH COURT vide W.P
NO: 6961/2020 Dated: 15-06-2021**

Lake Survey Number : 138



DETAILS:

1. Sketch prepared, as per the directions of DDLR letter NO: ಜತಾಂಸ/ಭೂಉನಿ/ತಾಂ(6) ವಿವ:21/2021 ದಿ:28-06-2021 and memo of ADLR, Bengaluru South NO: ಭೂ.ಸನಿ/ಪೋಡಿ/ಇತರೆ/273/2020-21, ದಿ: 02-05-2024
2. Survey department (land records) is only responsible for measurement and extent of the lake.
3. The measurement carried as per survey records in presence of B.B.M.P Engineer.
4. As fencing of the lake boundary is already done by B.B.M.P as per previous survey sketch during present field inspection that fence (chain And link fencing) is still in extents only left out area of the lake is now demarcated as encroachment as per survey document.
6. Lake details as below: (The details of the encroachment in lake are need to be verify from concerned authority).

SI No	Lake Sy No.	Extent of the lake		Details of Encroachment in Lake							Remarks
		As per Akarbhand (A-G)	As per Measurement (A-G)	Private Encroachment			Government Encroachment			Vacant Land A-G	
				Type of Encroachment	Block No.	Extent A-G	Type Encroachment	Block No.	Extent A-G		
1	138	1	23	-	-	-	-	-	-	1-23	

[Signature]
ಭೂಮಾಪಕರು
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
ಬೆಂಗಳೂರು ನಗರ.

[Signature]
ಸಹಾಯಕ ಎಂಜಿನಿಯರ್
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
ಬೆಂಗಳೂರು.

[Signature]
ಬೆಂಗಳೂರು ದಕ್ಷಿಣ ತಾಲ್ಲೂಕು
ಬೆಂಗಳೂರು.